

25X1

CONTROL NO.

TOP SECRET RUFF

DATE

7 January 19725X1

SUBJECT
AREA:

Ground Forces

IEG PI NOTICE

DISTRIBUTION:

All PIs

No. 3-76

TITLE/SIGNIFICANCE:

Armored Vehicle Test Facility for BMPs, BMDs, and BTR 60s

COMMENT: These test facilities are typical of those used in quality control for BMP, BMD, and BTR 60 production. The test facility is usually found within 10 nm of the production plant and indicates testing of the automotive and weapon systems of the vehicle. Each facility consists of (A) a vehicle test track with two parallel roads, (B) two machine gun firing points, (C) a firing-in butt and (D) a revetted magazine building. The enlarged inset is a second facility which better illustrates areas C and D. The identification of new similar test facilities should be reported.

25X1
25X1

LOCATION(S) Rubtsovsk Armored Veh
Test Fac
Kurgan Armd Veh Test Fac (BE

25X1
25X1
25X1

This is an informal communication intended for circulation within NPIC/IEG only. The conclusions are the opinion of the originator at the time of issue. Supporting or contrasting views are welcomed, and should be directed to the originator.

DIVISION
WGDBRANCH
CURBROOM
3S216

25X1

COPY NO. 25X1

400

REF 1327(E-00)

TOP SECRET RUFF

WARNING NOTICE
Sensitive Intelligence
and Methods Involved

25X1X1